## 8R 8R 8R 8R 8R 8R

Draw the Isometric view of the machine parts shown below figure 1. All dimensions are 9. in mm. [15] 8 81 Figure: 1 OR Draw the following orthographic projections of the machine part shown below figure 2. c) Side view. All dimensions are in mm. [15] a) Front view b) Top view 15 Figure: 2